

## ALPHABETICAL INDEX

## A

	Page
Accessory Tips .....	12-15
Acetylene Cylinders .....	2-16, 5-5
Acetylene Generator .....	5-4
Acid Etch Test .....	13-8
Acoustic Emission Testing .....	13-18
AC Welding .....	10-21
Air Carbon Arc Cutting (AAC) .....	10-108
Air Carbon Arc Cutting and Welding .....	2-25
Alloys Used for Hard Surfacing .....	12-29
Alternating Current Arc Welding Machines .....	5-25
Aluminum Brazing .....	11-44
Aluminum Soldering .....	11-47
Aluminum Welding .....	7-66, 11-41
Annealing .....	12-75
Application .....	12-72
Arc Blow .....	6-60
Arc Spot and Arc Seam Welds .....	3-20
Arc Welding .....	6-2
Automotive Exhaust Method of Cleaning .....	2-33

## B

Back Bend Test .....	13-11
Backhand Welding .....	6-37, 11-14
Back or Backing Welds .....	3-26

## B (cont)

Basic Weld Symbols .....	3-5
Brass and Bronze Welding .....	7-80, 11-50
Brazing .....	6-7, 11-26
Brazing Alloys .....	8-18
Brazing Gray Cast Iron .....	11-31
Brazing Malleable Iron .....	11-32
Bronze Surfacing .....	11-58
Butt Joint .....	6-21

## C

Carbon Arc Welding (CAW) .....	10-48
Cast Iron .....	7-59, 12-22
Cast Iron, Cast Steel, Carbon Steel, and Forgings .....	12-65
Categories of Metals .....	7-9
Chromium and Stainless Steel .....	12-22
Construction Lines .....	3-2
Construction of Symbols .....	3-12
Controlling Contraction and Expansion in Castings .....	6-41
Controlling Contraction in Sheet Metal .....	6-39
Copper Brazing .....	11-49
Copper Welding .....	7-81, 11-48
Corner Joint .....	6-22
Covered Electrodes .....	8-1
Cutting Armor Plate .....	12-33
Cutting Technique .....	12-5
Cutting Torch and Other Cutting Equipment .....	5-19

## D

DC Reverse Polarity Welding (See DC Straight and Reverse Polarity Welding)	
DC Straight and Reverse Polarity Welding .....	10-13
Description .....	1-1
Definition of Arc Welding .....	10-1
Determining the Weldable Parts .....	9-2
Dimensioning of Intermittent Fillet Welding .....	3-17
Direct Current Arc Welding Machines .....	5-23
Drawing and Quenching After Carburizing .....	12-79

## E

Eddy Current (Electromagnetic) Testing .....	13-17
Edge Joint .....	6-23
Electric Circuits .....	2-22
Electrodes, Covered (See Covered Electrodes)	
Electrodes and Their Use .....	5-37
Electrodes, Flux-Cored or Tubular (See Flux-Cored or Tubular Electrodes)	
Electrodes, Nonconsumable (See Nonconsumable Electrodes)	
Electron Beam Welding (EBW) .....	10-120
Elements of a Welding Symbol .....	3-5
Explosion Hazards .....	2-28
Extent of Fillet Welding .....	3-16
Extent of Welding Denoted by Symbols .....	3-12

## F

Ferrite Testing .....	13-18
Field Inspection of Welds and Equipment Repaired by Welding .....	13-1
Fillet Welding .....	11-15
Filling Treatment .....	2-37
Fire Hazards .....	2-7

## F (cont)

Flame Adjustment and Flame Types .....	11-6
Flame Descaling .....	12-25
Flame Hardening .....	12-24
Flame Machining (Oxygen Machining) .....	12-26
Flame Softening .....	12-24
Flame Straightening .....	12-24
Flame Strengthening .....	12-25
Flange Welds .....	3-28
Flash or Upset Welds .....	3-36
Flash Welding (FW) .....	10-116
Flash Welding Titanium .....	12-86
Flat Position Welding .....	6-31, 11-19
Fluorescent Penetrant Test .....	13-15
Flux-Cored Arc Welding (FCAW) .....	10-68
Flux-Cored or Tubular Electrodes .....	8-10
Forehand Welding .....	6-36, 11-13
Forges .....	5-51
Forging Tools .....	5-53
Free Bend Test .....	13-10
Friction Welding (FRW) .....	10-117
Fuel Gas Cylinders .....	2-20

## G

Gamma Ray Test .....	13-15
Gas Metal-Arc Welding (GMAW) Equipment .....	5-28
Gas Metal-Arc Welding (GMAW or MIG Welding) .....	10-54
Gas Metal-Arc Welding (GMAW) with Flux-Cored Wire .....	13-6

Gas Metal-Arc Welding (GMAW) with Solid-Core Wire .....	13-4
Gas Tungsten-Arc Welding (GTAW) Equipment (TIG) .....	5-26, 10-33
Gas Tungsten-Arc (TIG) Welding (GTAW) .....	10-33
Gas Welding .....	6-6, 13-4
General Gas Welding Procedures .....	11-1
Glossary .....	G-1
Groove Welds .....	3-22
Guided Bend Test .....	13-8

## H

Hard Surfacing .....	12-28
Hard Surfacing Procedure .....	12-30
Hardening .....	12-76
Hardness Tests .....	13-16
Hazards of Welding Polyurethane Foam Filled Assemblies .....	2-38
Health Protection and Ventilation .....	2-7
Heat Source .....	12-80
High Carbon Steels .....	7-49, 12-22
High Hardness Alloy Steels .....	7-52
High Yield Strength, Low Alloy Structural Steels .....	7-54
Horizontal Position Welding .....	6-32, 11-17
Hose .....	5-13
Hoses .....	2-21
Hot Chemical Solution Method of Cleaning .....	2-35
Hydrostatic Test .....	13-14

## I

Identification of Armor Plate .....	12-33
Identifying the Metal .....	9-2
Inch, Degree, and Pound Marks, Use of (See Use of Inch, Degree, and Pound Marks)	
Incomplete Penetration .....	13-2
Index .....	I-1
In-Service Cracking .....	6-53

## J

Joint Types .....	4-1
-------------------	-----

## L

Lack of Fusion .....	13-2
Lap Joint .....	6-23
Laser Beam Welding (LBW) .....	10-124
Lead Welding .....	11-56
Length of Fillet Welds .....	3-15
Location of the Weld With Respect to Joint .....	3-10
Location of Weld Symbols .....	3-12
Location Significance of Arrow .....	3-8
Low Carbon Steels .....	7-45

## M

Magnaflux Test .....	13-17
Magnesium Brazing .....	11-53
Magnesium Soldering .....	11-55
Magnesium Welding .....	7-84, 11-51
Magnetic Particle Test .....	13-14
Making Template Patterns .....	12-57
Malfunctions and Corrective Actions .....	12-16

MAPP Gas Cylinders .....	2-19
Marking of Safe Containers .....	2-37
Materials .....	12-15
Materials Used for Brazing, Welding, Soldering, Cutting, and Metallizing ....	D-1
Medium Carbon Steels .....	7-48
Melt-Thru Welds .....	3-27
Metal Cutting with Electric Arc .....	12-28
Metallizing and Welding Torch .....	12-14
Metals .....	1-2
Metals that Can be Hard Surfaced .....	12-29
Methods of Precleaning Containers Which Have Held Flammable Liquids .....	2-33
Miscellaneous Data .....	E-1
Muffle Jacket .....	12-80
Multilayer Welding .....	10-22
Multipass Welds .....	6-16

## N

Nick Break Test .....	13-12
Nickel Soldering .....	11-56
Nickel Welding .....	11-55
Nonconsumable Electrodes .....	8-14

## O

Operating the MIG Torch .....	5-32
Operation .....	12-15
Operation of Cutting Equipment .....	5-22
Other Welding Equipment .....	5-34
Other Welding Problems .....	6-68
Overhead Position Welding .....	6-32, 11-22

## O (cont)

Oxyacetylene Rivet Cutting .....	12-26
Oxyacetylene Welding Torch .....	5-11
Oxyfuel Cutting .....	11-33
Oxyfuel Welding Fluxes .....	11-12
Oxyfuel Welding Rods .....	11-12
Oxygen and Acetylene Regulators .....	5-8
Oxygen and its Production .....	5-7
Oxygen Cylinders .....	2-18, 5-8

## P

Parts of a Drawing .....	3-1
Personal Protective Equipment .....	2-1
Pipe Welding Procedures .....	12-61
Pipe Welding Processes .....	12-60
Plasma Arc Cutting (PAC) .....	10-102
Plasma Arc Cutting and Welding .....	2-24
Plasma Arc Welding (PAW) .....	10-38
Plug and Slot Welding Symbols .....	3-19
Porosity .....	13-3
Portable Welding Equipment .....	5-4
Positions for Pipe Welding .....	6-32
Potential Hazards .....	2-27
Preliminary Precautions .....	9-3
Preparation for Welding .....	12-54, B-1
Preparing the Clean Container for Welding or Cutting — Inert Gas Treatment .....	2-37



Preparing the Container for Cleaning .....	2-32
Procedure Guides for Welding .....	B-1
Procedures .....	12-66
Projection Welds .....	3-34
Properties of Armor Plate .....	12-32
Properties of Metals .....	7-1
Protective Measures .....	2-27
Protective Screens .....	2-24
Q	
Quenching After Carburizing .....	12-79
R	
References .....	A-1
References and General Notes .....	3-11
Regulator Malfunctions and Corrections .....	5-16
Resistance Seam Welds .....	3-31
Resistance Spot Welds .....	3-30
Resistance Welding (RW) .....	5-46, 6-12, 10-113, 12-80
S	
Scope .....	1-1
Sections of a Weld .....	6-15
Selecting the Proper Welding Procedures .....	9-2
Setting Up Welding Equipment .....	5-14
Setup .....	12-15
Shielded Metal-Arc Welding (SMAW) .....	10-23
Shutting Down Welding Apparatus .....	5-16
Silver Brazing (Soldering) .....	11-32

## S (cont)

Size of Fillet Welds .....	3-15
Sizing up the Job .....	9-1
Slag Inclusions .....	13-3
Soldering .....	8-16, 11-46
Solid Electrode Wires .....	8-7
Spot and Seam Welding Titanium .....	12-85
Spot Welding Magnesium .....	12-83
Standard Designation System for Aluminum and Aluminum Alloys .....	7-40
Standard Designation System for Copper and Copper Alloys .....	7-42
Standard Designation System for Magnesium and Magnesium Alloys .....	7-41
Standard Designation System for Titanium.....	7-45
Standard Designation System for Steel .....	7-37
Stationary Welding Equipment .....	5-1
Steam Method of Cleaning .....	2-34
Strengthening Riveted Joints in Armor Plate .....	12-54
Stresses and Cracking .....	6-47
Submerged Arc Flux Additives .....	8-16
Submerged Arc Welding (SAW) .....	10-83
Surface Contour of Fillet Welds .....	3-18
Surface Hardening .....	12-76
Surfacing Welds .....	3-28
Symbols, Construction of (See Construction of Symbols)	

## T

Tee Joint .....	6-24
Tempering .....	12-76
Tensile Strength Test .....	13-12
Termination of Intermittent Fillet Welding .....	3-18

Testing of Military Material .....	13-1
Thermit Welding .....	5-50, 6-12
Titanium Welding .....	7-94
Tool Steels .....	7-50
Tools and Equipment .....	12-14
Torch Malfunctions and Corrections .....	5-17
Troubleshooting Procedures .....	C-1
Types of Armor Plate .....	12-33
Types of Welds .....	6-25
U	
Undercutting .....	13-3
Underwater Cutting Technique .....	12-1
Underwater Welding Technique .....	12-2
Use of Carbonizing Compound Paste, NSN 6580-00-695-9268, and Isolating Paste, NSN 6850-00-664-0355, for Surface Hardening .....	12-77
Use of Inch, Degree, and Pound Marks .....	3-12
Using the Explosimeter .....	2-29
V	
Vertical Position Welding .....	6-32, 11-22
W	
Warnings .....	a
Water Method of Cleaning .....	2-35
Waster Plate Alloy Steel .....	12-22
Weld Accessibility .....	4-4
Weld-All-Around and Field Weld Symbols .....	3-11
Weld Failure Analysis .....	6-66
Weld Joint Design and Preparation .....	4-2

## W (cont)

Weld Joints .....	4-2
Welding Arcs .....	10-15
Welding Denoted by Symbols, Extent of (See Extent of Welding Denoted by Symbols)	
Welding Distortion and Warpage .....	6-42
Welding Equipment, Portable (See Portable Welding Equipment)	
Welding Equipment, Setting Up (See Setting Up Welding Equipment)	
Welding Equipment, Stationary (See Stationary Welding Equipment)	
Welding Face Hardened Armor Plate .....	12-48
Welding Homogeneous Armor Plate .....	12-36
Welding in Confined Spaces .....	2-13
Welding Machines .....	2-22
Welding Machines, Alternating Current Arc (See Alternating Current Arc Welding Machines)	
Welding Machines, Direct Current Arc (See Direct Current Arc Welding Machines)	
Welding Symbols, Plug and Slot (See Plug and Slot Welding Symbols)	
Welding Tips and Mixers .....	5-13
Welding with Constant Current .....	10-2
Welding with Constant Voltage .....	10-8
Welds, Arc Spot and Arc Seam (See Arc Spot and Arc Seam Welds)	
Weld Symbols, Location of (See Location of Weld Symbols)	
White Metal Welding .....	11-57
Working Pressures for Welding Operations .....	11-5

## X

X-Ray Test .....	13-14
------------------	-------

## Y

Y Fittings .....	12-15
------------------	-------